


AC-230 Mounting Tube Installation



1. Cut a 14" diameter opening in the application surface.
2. Place the mounting tube in the proper location as shown in the picture and tack weld in place. The mounting tube should be placed on the mounting surface with holes located in the 3 and 9 o'clock positions. This hole location will ensure the inlet to the horn is in the 6 o'clock position when the horn is mounted on a vertical surface.
3. Assemble the A sect., mounting flange, and B sect together with 5/16-18 x 1.5" hex head cap-screws, lock washers, and nuts.
4. Attach the mounting flange to the mounting tube with 5/16-18 x 1" hex head cap-screws, lock washers, and nuts.
5. Seal weld the remainder of mounting tube to the application surface.
6. Connect the air supply from the solenoid valve to the sound generator.